



**ASPHALT ROOFING  
EVALUATION**  
CONTROL #:RR0987654

<b>Attn:</b> John Homeowner <b>Company:</b>	<b>From:</b> ITEL Laboratories, Inc. <b>Phone:</b> 800-890-4835 <b>E-mail:</b> itelinfo@itelinc.com
<b>CLAIM#: N/A</b>	

<b>CUSTOMER INFO</b>	<b>Customer:</b> OTHER	<b>Cust. ID:</b> OTHER0001
<b>Adjuster:</b> N/A		
<b>Additional:</b> Homeowner <b>Rep:</b> John Homeowner <b>E-mail/Fax:</b> jhomeowner@email.com		
<b>Date Invoiced:</b> 7/16/2009 <b>Date Received:</b> 7/15/2009		

<b>LOSS INFO</b>	<b>Insured Name :</b> John Homeowner	<b>Claim # :</b> N/A
<b>Loss Location:</b> Anytown, MN 12345 <b>Area Damaged:</b> Front roof slope and separate garage north side		
<b>Loss Date:</b> 7/13/09		

<b>ORIGINAL PRODUCT IDENTIFICATION</b>	<input type="checkbox"/> The original product is no longer manufactured in the line King.
<b>Brand/:</b> NationalBrand <b>Type:</b> 3-Tab Standard	
<b>Line:</b> King (Discontinued) <b>Color:</b> Honey Brown	
<b>Warranty:</b> 25 years	
<b>Comments:</b> • The original product appears to be the NationalBrand King Fiberglass 3-Tab standard shingle. The product is no longer manufactured by NationalBrand.	

<b>SIMILAR PRODUCTS</b>	<input checked="" type="checkbox"/> Similar matches were found.
<b>Similarity Rating: 1</b>	<b>Suppliers:</b>
<b>Brand:</b> SimilarCo <b>Type:</b> 3-Tab Standard	10 miles away: SupplyCo (555) 555-1234 Anytown, MN 12354
<b>Line:</b> ZX-5 <b>Color:</b> Forest Brown	18 miles away: Roofs, Inc., (555) 555-0987 Anothertown, MN 12789
<b>Warranty:</b> 25 years	<b>Manufacturer Info:</b> SimilarCo / www.similarco.com / (800) 555-1357
<b>Similarity Rating: 2</b>	<b>Suppliers:</b>
<b>Brand:</b> Another Co Roof <b>Type:</b> 3-Tab Standard	18 miles away: Roofs, Inc., (555) 555-0987 Anothertown, MN 12789
<b>Line:</b> Econo Shield <b>Color:</b> Earth	<b>Manufacturer Info:</b> AnotherCo / www.anotherco.com / (800) 555-2468
<b>Warranty:</b> 25 years	
<b>Comments:</b> • Based on detailed color granule comparison, the selections listed are the closest possible in overall physical characteristics and color comparison to the original sample submitted.	
<b>* Similarity Rating:</b>	
1= Excellent match in pattern, color, and specifications (candidate for same slope repair).	
2= Good match, pattern and specifications exact or very close; color close (may be full elevation or non-adjacent slope replacement candidate).	
3= Comparable specification match, no suitable repair match found (quality indicator for warranty determination only).	

<b>SAMPLE ANALYSIS</b>
<b>Shingle type:</b> 3-Tab Standard <b>Width:</b> 36.00 <b>Height:</b> 12.00 <b>Warranty:</b> 25 <b>Specialty Granules:</b> None

<b>ADDITIONAL COMMENTS</b>
• Installers should verify visual and dimensional compatibility before purchasing and installing replacement products.