



ASPHALT ROOFING EVALUATION

CONTROL #:RR0987654

Attn: Jane Adjuster
Company: Insurance Co, Inc.

From: ITEL Laboratories, Inc.
Phone: 800-890-4835
E-mail: itelinfo@itelinc.com

CLAIM#: 123456789789

CUSTOMER INFO

Customer: Insurance Co. Cust. ID: INSCO0001

Adjuster: Jane Adjuster

Additional: RoofInstallers, Inc. Rep: Jim Vendor E-mail/Fax: jvendor@roofinstallersinc.com

Date Invoiced: 7/16/2009 Date Received: 7/15/2009

LOSS INFO

Insured Name : John Insured Claim # : 123456789789

Loss Location: Anytown, MN 12345 Area Damaged: Front roof slope and separate garage north side

Loss Date: 7/13/09

ORIGINAL PRODUCT IDENTIFICATION



The original product is no longer manufactured in the line King.

Brand/: NationalBrand Type: 3-Tab Standard

Line: King (Discontinued) Color: Honey Brown

Warranty: 25 years

Comments: • The original product appears to be the NationalBrand King Fiberglass 3-Tab standard shingle. The product is no longer manufactured by NationalBrand.

SIMILAR PRODUCTS



Similar matches were found.

Similarity Rating: 1

Brand: SimilarCo Type: 3-Tab Standard

Line: ZX-5 Color: Forest Brown

Warranty: 25 years

Suppliers:

10 miles away: SupplyCo (555) 555-1234 Anytown, MN 12354

18 miles away: Roofs, Inc., (555) 555-0987 Anothertown, MN 12789

Manufacturer Info:

SimilarCo / www.similarco.com / (800) 555-1357

Similarity Rating: 2

Brand: Another Co Roof Type: 3-Tab Standard

Line: Econo Shield Color: Earth

Warranty: 25 years

Suppliers:

18 miles away: Roofs, Inc., (555) 555-0987 Anothertown, MN 12789

Manufacturer Info:

AnotherCo / www.anotherco.com / (800) 555-2468

Comments: • Based on detailed color granule comparison, the selections listed are the closest possible in overall physical characteristics and color comparison to the original sample submitted.

* Similarity Rating:

1= Excellent match in pattern, color, and specifications (candidate for same slope repair).

2= Good match, pattern and specifications exact or very close; color close (may be full elevation or non-adjacent slope replacement candidate).

3= Comparable specification match, no suitable repair match found (quality indicator for warranty determination only).

SAMPLE ANALYSIS

Shingle type: 3-Tab Standard Width: 36.00 Height: 12.00 Warranty: 25 Specialty Granules: None

ADDITIONAL COMMENTS

• Installers should verify visual and dimensional compatibility before purchasing and installing replacement products.

INVOICE

Control Number: RR0987654

Claim #: 123456789789

ITEL Tax ID #: XX-XXXXXXX

Analysis Fee: \$ xx.xx

Shipping Fee: \$xx.xx

TOTAL DUE: \$XX.XX